


MECHANICAL REPORT MAZDA CX5 KDN 354K

The aforementioned vehicle vin **(KF2P-321826)** was brought to the Service Centre with an issue of oil leaks underneath it. Upon a thorough inspection, it was established that the source of the leak was from the mating surfaces of the cylinder block and the lower cylinder block on the rear of the engine as highlighted on the extract images below.

The remedy entails removal of the engine from the engine bay, dismantling of the engine oil sump to gain access to the lower cylinder block which has to be detached from the cylinder block



Actual images of the leakages as attached below.

