

Full Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:VANTAGE AUTO
Address:26 Lismore Street, Waltham,
Zip Code:8011
Telephone:03 377 9650
SN:960669801538
Test Time:02/17/2023 09:11:32

Vehicle Information

Year:2008
Make:Audi
Model:A5 Coupe
VIN:WAUZZZ8T98A026566
Odometer:82790 km
Vehicle Software Version:V10.12



Inspection Result

01 Engine Electronics 7 problems exist

- 1.U111300 Function Limitation Due To Received Malfunction Value
- 2.U111300 Function Limitation Due To Received Malfunction Value
- 3.P207000 Intake Manifold Tuning (IMT) Valve Stuck Open
- 4.U111300 Function Limitation Due To Received Malfunction Value
- 5.P115800 Manifold Abs. Press. Sens. - Implausible Signal
- 6.P006800 MAP/MAF - Throttle Position - Correlation
- 7.P164700 Checking Coding/Versions Of - in Powertrain

03 Brake Electronics 1 problems exist

- 1.03110 Active Steering Control Module

05 Access/Start Authorization 1 problems exist

- 1.03286 Right Front Exterior Door Handle Touch Sensor

14 Wheel Damping Electronics 1 problems exist

- 1.03264 Function Shut-Off

16 Steering Column Electronics Systems 1 problems exist

- 1.00895 CCS/ADR Control Unit

1B Active Steering 1 problems exist

- 1.01087 Basic Settings Not Carried Out

42 Driver's Door Electronics 1 problems exist

1.00920 Heated Outside Mirrors

46 Comfort System Central Control Module 1 problems exist

1.02616 Unlocking Fuel Tank Cap

47 Sound System 1 problems exist

1.00003 Control Module

The following systems are OK:

1.02 Transmission Electronics

2.06 Seat Adjustment, Passenger's Side

3.07 Display/Control Head

4.08 Climate Control Module

5.09 Electronic Central Electric

6.0E Media Player 1

7.10 Parallel Parking 2

8.15 Airbag

9.17 Instrument Cluster

10.19 Data Bus OBD Interface

11.1E Media Player 2

12.36 Seat Adjustment, Driver Side

13.37 Navigation

14.52 Passenger's Door Electronics

15.53 Brake Button

16.55 Headlamp Range Control

17.56 Radio

18.57 TV Tuner

19.6C Rear View Camera System