



27 Stanmore Road
Christchurch Canterbury 8011
GST Registration No.: 132263159
Tel: 03 381 1333
Email: admin@aceomatic.co.nz

ESTIMATE #2348

Issue Date: 24/05/2023

Order Number: 43918

PREPARED FOR:

IBC Japan

Tel: 027 229 2061

Mobile: 027 229 2061

Email: GKeatley@ibcauto.com

VEHICLE: Vehicle Owner: IBC Japan
Reg No: WVWZZZAUZEW088284
VIN: WVWZZZAUZEW088284
Model: VOLKSWAGEN GOLF
Body Type: Hatchback
Year: 2013
Odometer: 92,124 Kms

Description	Qty.	Disc.	Unit Price	Amount
DUAL MASS FLYWHEEL	1.0	10%	\$1,230.00	\$1,107.00
DUAL CLUTCH	1.0	10%	\$1,026.30	\$923.67
INPUT SEAL (OAM) 40x56x8	1.0	10%	\$20.78	\$20.78
INPUT SEAL (OAM) 20.5x28x7	1.0	10%	\$20.77	\$20.77
DSG Fluid (dry clutch)		0%		\$69.00
LABOUR		10%		\$1,188.00

Road test vehicle. Remove transmission from vehicle. Remove check and replace dual mass flywheel/clutch. Refit to vehicle. Fill with fluid. Road test vehicle and perform reset/relearn.

Subtotal	\$3,329.22
GST	\$499.38
Total	\$3,828.60

Please Note: The above estimate has been prepared using parts we consider may be required during the repair of your transmission. Your particular unit may require parts not listed or may not require some parts listed.