

DRAFT QUOTE

Key Alliance Pro Ltd
 10 Doncaster Street
 Mangere
 Auckland 2022
 NEW ZEALAND

Date
 17 Aug 2023

Quote Number
 QU-0942

Reference
 PDY326 BMW 530i

GST Number
 134-662-763

9C Andromeda Crescent,
 East Tamaki
 Manukau 2013
 e:
 euro.motive@outlook.com
 m: +64212833611
 ph: 092122034

Description	Quantity	Unit Price	Amount NZD
F: abs & traction control light on C: active steering control unit soaked with water R: connect diagnostic machine, follow test procedure on active steering - carry out initialisation of active steering, failed - check fuse of active steering, ok - remove driver seat to visually inspect control unit, found soaked with water, requires replacement - requires remedy of water ingress to avoid control unit getting soaked with water F: center screen flickers, stays on "BMW" logo C: head unit failed R: carry out inspection of head unit, confirmed fault - carry out function test of screen through diagnostic machine, failed - remove head unit, inspect plug connections, ok - fit donor head unit, screen ok - head unit internal fault, requires replacement F: transmission staying on 1 gear C: unable to replicate fault R: road tested vehicle to verify fault, unable to replicate fault as per complain - connect vehicle to diagnostic machine - no fault on transmission, requires further road test to verify fault	1.00	230.00	230.00
Diagnostic Scan Tool Fee	1.00	59.00	59.00
SUB TOTAL	0.00	289.00	0.00
Carry out replacement of active steering control unit & coding/programing	1.00	351.00	351.00
Active Steering Control Unit - used/recycled	1.00	600.00	600.00
SUB TOTAL	0.00	951.00	0.00
Carry out replacement of head unit & coding/programing	1.00	351.00	351.00
Head unit - used/recycled	1.00	725.00	725.00

Description	Quantity	Unit Price	Amount NZD
.	0.00	1,076.00	0.00
Remedy water ingress - trace water ingress - found coming from RH/F & RH/R door panels - remove door cards - reseal weather curtain - water test, ok - dry up carpet for 5 days - check and inspect RH/F and RH/R doors for any water, found none	1.00	440.00	440.00
SUB TOTAL			
Carry out replacement of gearbox	1.00	739.50	739.50
Gearbox - used/recycled	1.00	2,205.00	2,205.00
Transmission Oil	8.00	35.50	284.00
Parts Freight	1.00	19.99	19.99
Consumables	1.00	9.99	9.99
SUB TOTAL			
		Subtotal	6,014.48
		TOTAL GST 15%	902.18
		TOTAL NZD	6,916.66

Terms

This estimate is not guaranteed. The price named in the estimate is an approximation of the repair requirements as described by the client. The actual cost may change after all of the project elements have been negotiated and finalized. The client will be informed of any changes in cost in advance.

This estimate is valid for x days

Once quote has been accepted and repairs has been done, client must collect vehicle with full payment. Failure to complete payment upon completion of the repairs can incur storage fee of \$30+gst per day.