



27 Stanmore Road
 Christchurch Canterbury 8011
 GST Registration No.: 132263159
 Tel: 03 381 1333
 Email: admin@aceomatic.co.nz

ESTIMATE #5338
 Issue Date: 20/10/2025

PREPARED FOR:
Key Alliance Pro Ltd
 15 Edmund Road
 Rotorua Bay of Plenty 3015
 Email: kapaccounts@keyalliancepro.co.nz

VEHICLE: Vehicle Owner: Key Alliance Pro Ltd
 Reg No: RKT313
 Chassis: E12-450942
 VIN: 7AT0DH79X24450942
 Model: NISSAN NOTE
 Body Type: Hatchback
 Year: 2016

Description	Qty.	Disc.	Unit Price	Amount
OVERHAUL KIT (CVT7/JF015E) W/OUT PISTONS	1.0	10%	\$429.16	\$429.16
VALVE BODY (CVT7/JF015E) 2 SENSOR	1.0	10%	\$1,305.31	\$1,305.31
FILTER (JF015E) NISSAN/SUZUKI SWIFT CVT	1.0	10%	\$35.26	\$35.26
FILTER EXTERNAL (CVT7/JF015E/RE0F11A)	1.0	10%	\$25.42	\$25.42
PISTON PRIMARY SHAFT UPGRADE (JF015E)A/M	1.0	10%	\$161.86	\$161.86
PUMP FLOW CONTROL VALVE (RE0F10A/JF011E)	1.0	10%	\$74.17	\$74.17
CODING	1.0	0%	\$195.00	\$195.00
CLEANING FLUID & SUNDRIES	1.0	0%	\$95.00	\$95.00
CVT Fluid		0%		\$188.00
LABOUR		10%		\$2,376.00

Remove Transaxle unit from vehicle and strip down. Clean and inspect parts. Reassemble sub assemblies with new seals and parts as listed. Strip down valve body. Clean and check valves, reassemble. Overhaul pump. Check over planet gears and shafts. Reassemble unit and refit to vehicle. Road test and set adjustments.

Subtotal	\$4,885.18
GST	\$732.78
Total	\$5,617.96

Please Note: The above estimate has been prepared using parts we consider may be required during the repair of your transmission. Your particular unit may require parts not listed or may not require some parts listed.