

Tax Invoice



Invoice Date: 10/12/2025

Invoice Number: INV 4041

📞 022 599 9000

✉ info@hamiltonautocentre.co.nz

🏠 1 Norris Avenue, Te Rapa, Hamilton 3200

Hamilton Auto Centre
NZBN: 9429042036265
GST Number: 118085264

Contact Name: Dave Allen Motors (Dave Allen Motors)
Contact Number: 0800 227 000
Address: 5 Norris Avenue, Te Rapa, WAIKATO, 3200

Registration: 18968
Vehicle Details: 2014 BMW 328i

Engine Knocking Noise Investigation

Customer Concerns:

1. Engine making a knocking noise, sounds like a diesel engine.
2. Dashboard warning for front and rear brake pads.

Technician Findings:

1. Engine Knocking Noise:

Investigated reported knocking noise.
Found engine oil leaks from:

Rocker cover gasket
Tappet cover gasket
Other possible areas

Knocking detected from engine bearings during inspection.

Based on leak severity, it is suspected the engine may have been run with low engine oil, which can cause bearing wear or internal damage.

2. Brake Warning Light – Front & Rear:

Inspected brake system as dashboard shows brake pad warning.
Brake pads are in good condition and do not require replacement now.
Warning light is caused by worn brake pad wear sensors.
Sensors were not replaced previously when brake pads were changed.

Recommended Action:

Replace front and rear brake pad wear sensors to clear the warning message.

Description	Qty	Price	Total
Engine Knocking Noise Investigation	1.00	85.00	85.00
		Subtotal	85.00

Due Date: 20/01/2026

Goods and services remain property of Hamilton Auto Centre until the invoice is paid in full.

Bank Acc. No: 02-0316-0700812-000

Bank Acc. Name: Taj Motors Ltd (T/A HAC)

Total GST \$12.75

Grand Total NZD **\$97.75**