

AUTO SUPER SHOPPE MAIDSTONE

MAP UPPER HUTT LTD

4 GOODSHED ROAD
UPPER HUTT 5018

Email: ruory@autosmaidstone.co.nz
www.autosmaidstone.co.nz

Phone: 04 528 4070
Mobile:
Fax: 04 528 4070

May 27, 2019

Estimate

2680

King Street Cars
14-16 King Street
Upper Hutt 5018

Phone: 5277115
Mobile:

Description: VW Transmission

VIN No
Chassis/Mo

Customer Id: KING

Description	Qty	Price	Total
<i>2009 VW Golf, Chassis: WVWZZZ1KZ9M308707</i>			
<i>Scan and check for fault codes, codes P0840 and P0841 relating to transmission pressure faults present. Seek advice from Volkswagon and independent transmission specialist. Both advised transmission mechatronic unit faulty and requires replacement.</i>			
Scan tool (ECU Codes)	1.00	35.00	35.00
Transmission Repair	1.00	4,099.75	4,099.75

Note

Price based on having transmission specialist in Porirua replace and does not include cost of getting vehicle to specialist and back again,

Valid Until 26/06/2019

Labour \$79.00
Parts \$4,134.75

By accepting this estimate you are deemed to have accepted our terms of trade which are attached and on display at the workshop

Sub-Total \$4,213.75
GST \$632.06

Printed: 27/05/19 5:02PM

This is NOT a Tax Invoice

TOTAL \$4,845.81