

RICCARTON

Auto Electric Centre Ltd

5 Leslie Hills Drive, Riccarton, Christchurch
 P.O. Box 8381, Riccarton, Christchurch
 Telephone 03 348 7736, Fax 03 348 7178

Wheeler Motor Company
 P.O.Box 7536
 Sydenham

TAX INVOICE

GST No 49-107-765

YOUR NO.	INVOICE NUMBER	TERMS	DATE	PG.
7896	00132066	Net 20th after EOM	31/05/2019	Page 1 of 1
QTY.	DESCRIPTION	PRICE	UNIT	TOTAL
1	Toyota Camry. Checked codes- Faulty Hybrid battery code. (code wont clear) Confirm faulty hybrid battery. Remove from customers vehicle AVV50-1008579 and fit it to stock vehicle and stock vehicle battery to customers car. Reassemble vehicle and test O.K	\$45.00		\$45.00
5.5	Scan Fee	\$80.00	Hr	\$440.00
1	Labour			
	Priced new Battery from toyota at \$8400 plus gst advised Wheelers			
Bank Account Number For Direct Credit Payments: 06 0821 0043569 00		SALE AMOUNT	\$485.00	
		GST	\$72.75	
		TOTAL AMOUNT	\$557.75	
		PAID TODAY	\$0.00	
		BALANCE DUE	\$557.75	