

Full Diagnostic Report

The Report is created by **THINKCAR**

Repair Shop

Shop Name:VANTAGE AUTO
Address:26 Lismore Street, Waltham,
Zip Code:8011
Telephone:03 377 9650
SN:960669801538
Test Time:02/17/2023 09:57:30

Vehicle Information

Year:2008
Make:Audi
Model:A5Coupe
VIN:WAUZZZ8T98A026566
Odometer:82790 km
Vehicle Software Version:V10.12



Inspection Result

01 Engine Electronics 5 problems exist

- 1.U111300 Function Limitation Due To Received Malfunction Value
- 2.U111300 Function Limitation Due To Received Malfunction Value
- 3.P207000 Intake Manifold Tuning (IMT) Valve Stuck Open
- 4.P164700 Checking Coding/Versions Of - in Powertrain
- 5.U111300 Function Limitation Due To Received Malfunction Value

03 Brake Electronics 1 problems exist

- 1.03110 Active Steering Control Module

16 Steering Column Electronics Systems 1 problems exist

- 1.00895 CCS/ADR Control Unit

1B Active Steering 1 problems exist

- 1.01087 Basic Settings Not Carried Out

37 Navigation 1 problems exist

- 1.00867 Connection To ABS Control Unit

47 Sound System 1 problems exist

- 1.00003 Control Module

The following systems are OK:

- 1.02 Transmission Electronics

2.05 Access/Start Authorization
3.06 Seat Adjustment, Passenger's Side
4.07 Display/Control Head
5.08 Climate Control Module
6.09 Electronic Central Electric
7.0E Media Player 1
8.10 Parallel Parking 2
9.14 Wheel Damping Electronics
10.15 Airbag
11.17 Instrument Cluster
12.19 Data Bus OBD Interface
13.1E Media Player 2
14.36 Seat Adjustment, Driver Side
15.42 Driver's Door Electronics
16.46 Comfort System Central Control Module
17.52 Passenger's Door Electronics
18.53 Brake Button
19.55 Headlamp Range Control
20.56 Radio
21.57 TV Tuner
22.6C Rear View Camera System