



# Estimate #3526

Issue Date: 28/02/2023

26 Lismore Street  
Christchurch Canterbury 8011  
GST Registration No.: 108844469  
Tel: 033779650  
Email: info@vantageauto.co.nz

**PREPARED FOR:**

**IBC AUTOS**

Tel: 0272292081

Mobile: 0272292081

Email: sales@ibcauto.com

**FOR:**

A5 ESP ISSUES / DECLARATION

Vehicle Owner: IBC AUTOS

VIN: WAUZZZ8T98A026566

Model: AUDI A5

Description	Qty.	Unit Price	Amount
MANIFOLD DRIVE UNIT	1.0	\$892.00	\$892.00
INJECTOR	6.0	\$464.00	\$2,784.00
SEAL KIT	6.0	\$72.00	\$432.00
FRE - FRE FREIGHT LOCAL SPRINT	1.0	\$45.00	\$45.00
SCAN DIAGNOSTIC FEE - SCAN DIAGNOSTIC FEE DIAGNOSTIC FEE	1.0	\$56.52	\$56.52
SUNDRIES - PPE / CONSUMABLES / STATIONARY / OHS / ETC	1.0	\$7.50	\$7.50
LABOUR - LABOUR LABOUR			\$874.13

WORK THROUGH MIXTURE , STEERING AND MANIFOLD CODES.  
PRICE TO REPAIR AS ABOVE.

<b>Subtotal</b>	<b>\$5,091.15</b>
<b>GST</b>	<b>\$763.67</b>
<b>Total</b>	<b>\$5,854.82</b>