



Estimate 34128

Owner

Invoice to

Key Alliance Pro

Mfabriga@keyalliancepro.co.nz

Home Phone	Mobile Phone	Email	Start date 17/01/2025	End date
Estimate By Office - Peter Coombe	Estimate Date 30/01/2025			

SUBARU Legacy White

BRM-031055

Body style Station Wagon	Odometer	Paint Code	VIN BRM-031055
Cylinders	Manufactured January 2014	Trim Code	Engine Number

Interior Inspection

	Amount
NZ Entry Compliance Inspection	201.75
	201.75

Compliance Repair

	Amount
Remove and Replace Rear Bumper reinforcement	106.25
Remove and replace steering rack and steering column to remove play	425.00
NOTE: second hand parts need to be bench tested for suitability prior to installation.	Report On
	531.25

Miscellaneous

	Amount
Consumables & Clips	15.00
Re-assignment of Debtor Process	98.00
	113.00

New Parts

Description	Supply	Part Number	Qty	Amount
Rear Bumper Reinforcement Bar SUBARU LEGACY	New		1	193.75
Freight Inwards - Rear Bumper Bar	New	NZC	1	42.00
Steering Rack & Steering column Replacement - second hand	New	TBC	1	805.00
Freight Inbound Steering Rack	New	NZC	1	35.00
		Total New Parts		1075.75

Total Labour	733.00
Total Parts / Other	1188.75
Sub Total	1921.75
Total Excluding GST	1921.75
GST Amount	288.26

Total \$

2210.01

This quote is valid for 7 days from date of issue. Please confirm your acceptance by return email to secure your booking hello@vssnorth.co.nz. Please pay online to VSS North Limited 12-3427-0073923-00, please state the estimate Number, Name, & Reference with your payment