

VIN Number: MNTCB4D23Z0002203

Item	Parts Number	Description	Price (JPY)	Price (USD)	Comment
1	F510M-4KDMA	Hood			Parts number invalid. <a href="#">No similar parts in Japan.</a>
2	26010-1JA2A	Lamp Assy RH			Parts number invalid. <a href="#">No similar parts in Japan.</a>
3	26060-1JA2A	Lamp Assy LH			Parts number invalid. <a href="#">No similar parts in Japan.</a>
4	21476-00Q0H	Fender Front RH			Parts number invalid. <a href="#">No similar parts in Japan.</a>
5	F3101-ZW5MA	Fender Front LH			Parts Applicable to: Nissan Europe (RHD/LHD) Nissan General (LHD) <a href="#">No similar parts in Japan.</a>
6	26150-00Q0A	Fog Light Assy RH			Parts number invalid. <a href="#">No similar parts in Japan.</a>
7	26155-00Q0D	Fog Light Assy LH			Parts number invalid. <a href="#">No similar parts in Japan.</a>
8	26910-4JVOA	Bracket Fog Lamp			Parts number invalid. <a href="#">No similar parts in Japan.</a>
9	26915-4JVOA	Bracket Fog Lamp			Parts number invalid. <a href="#">No similar parts in Japan.</a>
10	62022-M7761	Bumper Front			Parts Applicable to: Nissan Europe (LHD) <a href="#">No similar parts in Japan.</a>
11	21477-EB800	Shroud Lower			Parts Applicable to: Nissan Europe (RHD/LHD) Nissan General (RHD/LHD) <a href="#">No similar parts in Japan.</a>
12	92100-AX800	Condenser & Liquid			Parts Applicable to: Nissan Europe (RHD/LHD) <a href="#">No similar parts in Japan.</a>
13	62890-4JA0A	Emblem Front			Parts number invalid. <a href="#">No similar parts in Japan.</a>
14	F2520-4KEMB	Support Radiator			Parts number invalid. <a href="#">No similar parts in Japan.</a>
15	62550-4JA5A	STAY Assembly			Parts number invalid. <a href="#">No similar parts in Japan.</a>
16	62510-AA000	Brace Assy R/CO	13,200	122	Parts Applicable to: Nissan Japan
17	92450-BV81C	Pipe Front Cool			Parts number invalid. <a href="#">No similar parts in Japan.</a>
18	92480-3JA0A	Hose Flexible L			Parts Applicable to: Nissan Canada Nissan General (RHD/LHD) Nissan USA <a href="#">No similar parts in Japan.</a>
19	92490-3JA0A	Hose Flexible H			Parts Applicable to: Nissan Canada Nissan General (RHD/LHD) Nissan USA <a href="#">No similar parts in Japan.</a>
20	92131-AY600	Tank Assy Liquid			Parts Applicable to: Nissan Europe (RHD/LHD) <a href="#">No similar parts in Japan.</a>

Item	Parts Number	Description	Price (JPY)	Price (USD)	Comment
21	13035-00Q0A	Cover Assy Front			Parts number invalid. <a href="#">No similar parts in Japan.</a>
22	16500-BN700	Air Cleaner			Parts Applicable to: Nissan Europe (LHD) <a href="#">No similar parts in Japan.</a>
23	16576-4JA1A	Air Duct			Parts number invalid. <a href="#">No similar parts in Japan.</a>
24	21060-EB70B	Fan Cooling			Parts Applicable to: Nissan General (RHD/LHD) <a href="#">No similar parts in Japan.</a>
25	21710-BM400	Tank Assembly Reserve			Parts Applicable to: Nissan Europe (RHD/LHD) Nissan General (RHD/LHD) <a href="#">No similar parts in Japan.</a>
26	21469-ED31A	Duct Air Intake			Parts number invalid. <a href="#">No similar parts in Japan.</a>
27	21497-BR00A	Seal Radiator L			Parts Applicable to: Nissan Europe (RHD/LHD) <a href="#">No similar parts in Japan.</a>
28	21606-5FLOA	Oil Cooler Assembly			Parts number invalid. <a href="#">No similar parts in Japan.</a>
29	F4151-4JAMA	Hood Ledge Upper			Parts number invalid. <a href="#">No similar parts in Japan.</a>
30	65601-4JAOA	Male Assembly Hood			Parts number invalid. <a href="#">No similar parts in Japan.</a>
31	14041-3JAOA	Cover Intake MA			Parts Applicable to: Nissan General (LHD) <a href="#">No similar parts in Japan.</a>
32	15257-00QAA	Tank Vacuum			Parts number invalid. <a href="#">No similar parts in Japan.</a>
33	21743-JF00A	Hose Reserve TA	1,200	11	Parts Applicable to: Nissan Canada Nissan Europe (RHD/LHD) Nissan General (RHD/LHD) Nissan USA Nissan Japan
34	62223-4JAOA	Bracket Front B			Parts number invalid. <a href="#">No similar parts in Japan.</a>
35	21496-JF10A	Seal Radiator	500	5	Parts Applicable to: Nissan Canada Nissan Europe (RHD/LHD) Nissan General (RHD/LHD) Nissan USA Nissan Japan
36	62310-HV31D	Grille Assembly Front			Parts number invalid. <a href="#">No similar parts in Japan.</a>
37	21476-00Q0H	Shroud Radiator			Parts number invalid. <a href="#">No similar parts in Japan.</a>
38	21460-AV601	Radiator Assembly			Parts Applicable to: Nissan Europe (RHD/LHD) <a href="#">No similar parts in Japan.</a>

Subtotal	14,900	137
Shipping cost to Kenya (DHL)	28,600	264
Shipping cost to Kenya (EMS)	19,600	181
Handling cost	2,000	18
<b>Total cost (DHL)</b>	<b>45,500</b>	<b>419</b>
<b>Total cost (EMS)</b>	<b>36,500</b>	<b>336</b>