

Date: 7/23/2019 Client: IBC JAPAN Chassis No.: RM4-1002521 ✓ Model Code: DBA-RM4

Make/Name: HONDA / CR-V Year of 1st Reg: 2012.3 Odometer on E.C: 52.500 ✓

Color: White Engine No.: K24A-9522530 Year: 2012 Odometer: 88008 (km) ✓

Line Inspection Pass/Ok "✓", Fail "x"

<input checked="" type="checkbox"/> Brake System												
F L	360	kg	R	350	kg	Sum of main brake (vehicle weight+55k)	1595	x0.5=	798	< sum of brake=	1260	<input checked="" type="checkbox"/>
R L	380	kg	R	390	kg	Sum of parking brake (vehicle weight+55kg)	1595	x0.2=	319	< sum of parking brake=	470	<input checked="" type="checkbox"/>
P L	330	kg	R	240	kg	Sum of R wheel brake	620	x0.1=	62	< sum of R wheel brake=	570	<input checked="" type="checkbox"/>
M L		kg	R		kg	Pull: Front (axis weight+55kg)	975	x0.08=	78	> Difference b/w R and L axis=		<input type="checkbox"/>
						Pull: Rear (axis weight)	620	x0.08=	50	> Difference b/w R and L axis=		<input type="checkbox"/>

<input checked="" type="checkbox"/> Speedometer	<input checked="" type="checkbox"/> Side Slip	<input checked="" type="checkbox"/> Exhaust	<input checked="" type="checkbox"/> Head Light
Difference	IN	CO	Attachment Height
	2	0	R
	mm	ppm	85 cm
	OUT	Diesel	L
	mm	%m-1	85 cm
km/h			
			Optical Axis (Under)
			Optical Axis (RL)
			L-R
			10 cm
			400 x100cd
			E-R
			0 cm
			400 x100cd

Visual Inspection Pass/Ok "✓", Fail "x", Nil "-"

Tyre

Condition: Good / Puncture(x)

Wheel: Alloy / Cover / Steel

Wheel Origin: Original / After Market

Tyre Type: Normal / Snow

Run-Flat

Tyre Treads: (F8 mm/R mm)

Size: 25 165 R17

Exterior

Lights

Head Lamp

Indicator

Rear

Brake

Plate

Dash Lamp

ABS

SRS

Engine

Water Temp

Other ()

Interior

Steering (R · L)

Power Steering

Horn (100 dB)

Gauges/Lights

Climate Control

SW

Windows

Wipers

Mirrors (Back and Sides)

A/T:M/T

Safety Belts

Brake Pedal

Brake Booster

Clutch Pedal·Function

Room Lamp

A/C

Audio·Navigation

HIC

Engine

Engine Condition

Fuel (G · D · HB)

Oil: Ok / Emp / Dty / Leak

Radiator: Ok / Emp / Leak

Fan Belt

Battery

Master Cylinder

~~Carburetor~~

Fuel Pipes

Injection Pump

Wiring Harness

Generator

Cooling System

Manifolds

Lubrication System

Other ()

CFC (R-134a · R-12)

Underbody

Tyre Condition

Wheel Bearing

Springs

Shock Absorber

Suspension Fixing

Torque Rod

Gear Box

Steering Rod/Arm

Disk Brake

~~Drums~~

Wheel Cylinder

Brake Rod / Cable

Brake Hose / Pipe

Park Brake System

Front axle

Drive Shaft

Propeller Shaft

Axle Housing





Differential

Fuel Tank

Exhaust System

Air Suspension

Air Brake



Equipment

Jack

Tyre Iron

Repair Kit · Spare Tyre

Comments

RF

RR

LR

LF

B/T No. 0507161

アイドリング車内 (64 dB)

アイドリング車外 (73 dB)

Radiation Check (μSv/h)

F.Grill

Bonnet

F.Left Tyre

F.Right Tyre

R.Left Tyre

R.Right Tyre

Photo (F/R/Interior/Odo)

Remarks (Reason for Fail) :

Interior:	Air	Vacuum	Steam
Exterior:	Air	Vacuum	Steam

Quarantine Inspection

Interior	Pass	Fail
2nd	Pass	Fail
3rd	Pass	Fail
Exterior	Pass	Fail
2nd	Pass	Fail
3rd	Pass	Fail
30 Days	Pass	Fail

Sticker Number:

D=Damage CR=Crack R=Rust
F=Repair A=Scratch U=Dent
1:~3cm, 2:~10cm, 3:~40cm, 4:40cm~

1st Inspection <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	2nd Inspection <input type="checkbox"/> Pass <input type="checkbox"/> Fail	3rd Inspection <input type="checkbox"/> Pass <input type="checkbox"/> Fail
Inspector Signature	Inspector Signature	Inspector Signature
Date <u>2019 17 03</u>	Date / /	Date / /