

www.exportpart.com

sales@exportpart.com

RAM 1500 2020 V6

33586 USD




VEHICLE DETAILS

VIN	1C6RRFBG0LN*****
Year	2020
Mileage	5
Series	Big Horn

Body style	Crew Cab Pickup
Exterior color	Diamond black
Interior color	Black

VEHICLE LOCATION

Country	 United States
State	OH
ZIP code	44906
Closest Port	New York (US)
Distance to port, in miles	497

MECHANICAL DETAILS

Engine name	3.6L V6 24V MPFI DOHC
Cylinders	6
Displacement	3.6
Transmission	Automatic
Drivetrain	4WD

VEHICLE EQUIPMENT

- ✓ abs brakes
- ✓ am/fm radio
- ✓ cloth bench seat
- ✓ dual front impact airbags
- ✓ front & rear rubber floor mats
- ✓ front fog lights
- ✓ fully automatic headlights
- ✓ illuminated entry
- ✓ manual adjust 4-way front passenger seat
- ✓ outside temperature display
- ✓ panic alarm
- ✓ passenger vanity mirror
- ✓ quick order package 23z big horn,6 speakers
- ✓ rear anti-roll bar
- ✓ remote keyless entry
- ✓ split folding rear seat
- ✓ tilt steering wheel
- ✓ voltmeter,3 rear seat head restraints,4 way front headrests
- ✓ air conditioning
- ✓ brake assist
- ✓ delay-off headlights
- ✓ dual front side impact airbags
- ✓ front anti-roll bar
- ✓ front seat back map pockets
- ✓ gps antenna input
- ✓ leather steering wheel
- ✓ manufacturer's statement of origin
- ✓ overhead airbag
- ✓ parkview rear back-up camera
- ✓ power door mirrors
- ✓ radio: uconnect 3 w/5 display
- ✓ rear seat center armrest
- ✓ remote start system
- ✓ steering wheel mounted audio controls
- ✓ traction control,4-wheel disc brakes
- ✓ wheels: 18 x 8
- ✓ alloy wheels
- ✓ bumpers: chrome
- ✓ driver door bin
- ✓ electronic stability control
- ✓ front center armrest w/storage
- ✓ front wheel independent suspension
- ✓ heated door mirrors
- ✓ low tire pressure warning
- ✓ occupant sensing airbag
- ✓ overhead console
- ✓ passenger door bin
- ✓ power steering
- ✓ rear 60/40 folding seat
- ✓ rear step bumper,4g lte wi-fi hot spot
- ✓ speed control,48v belt starter generator
- ✓ telescoping steering wheel
- ✓ variably intermittent wipers,3.21 rear axle ratio,

CONDITION

Damage Amount	Frame Damage	Vehicle Grade	Autograde	Inspection Date
N/A	N/A	N/A	No	Oct 17, 2019

PICTURES





