

Name (Mr/Mrs/Ms/Miss)  NZ Transport Agency Agent code

Address  Location  **QR**

Inspection Date  **18/11/18** **3222241**

Chassis  **5722368** ~~ZVW30-1937306~~ Reference  **DA152**

Vehicle Type  **07** N/U/R or S  **U** Border Check Date  **10/10/18** **5939811**

1st NZ Reg  M/Y  Engine No  **27R-~~6361774~~**

Previous Country  **JPN** 1st Reg Date  **1/2014** M/Y  Seats  **05**

Basic Colour  **SILVER WHITE** Second Colour  **-**

Make  **TOYOTA** Model  **PRIUS**

Sub Model  **HYBRID** Indust Model  **DAA-ZVW30** Variant  **25**

Vehicle Year  **2014** Body Type  **HA** Imported LHD  **N**

GVM  **1625** CC Rating  **1797** Engine Type  **09** Altern Fuel

Assembly Type  **01** Odometer  **80757** ~~69009~~ Odo Unit  **K**

Class  **MA** No of Axles  Original Country  **JPN**

Test Regime  **DDAA** FC Urban  FC Ext Urban  FC Combined

A/C Fitted  **Y** FIS  **Y** Y/N  Special Permits

Gas Type  **HFC134** Tare  **1350**

Completed VIN Number  **7A70H637X19722368**

**Defects to be remedied**

Section	Defect	Rechecked		VCC Signature and ID
		Pass	Fail	
①	Both rear tyres worn.	Pass	Fail	
②	New under seal covering all under body, sign of repair in some few places. - supply repair certificate report	Pass	Fail	
③	Remove non comply tint	Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	
		Pass	Fail	

Comments  **Recommend to fixed tyres**