

Customer Details	Stadium	Order No.	Site No. 6058
TBC			

VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS, OR ANOTHER COMPLETE INSPECTION IS TO BE CARRIED OUT



Vehicle Information												
VIN	7ATOC12HX24149747											
Chassis	DEJFS-149747					Reference	MS6058					
Vehicle Type	07		N/U/R or S	4		Border Check	5-7-24					
1st NZ Reg						Engine No	P3-30249731					
Prev Country	JPN		1st Reg Date	2/13		Seats	5					
Basic Colour	White					Second Colour						
Make	Mazda					Model	Demio					
Sub Model						Indust. Model	DBA-DEJFS		Variant	004		
Vehcl. Year	2013		Body Type	HA		Imported LHD	N					
GVM	1295		CC Rating	1298		Engine Type	01		Altern Fuel	-		
Assembly Type	1		Odometer	51028.		ODO Unit	K					
Class	MA		No. of Axles	2		Orig. Country	JPN					
A/C Fitted	Y		FIS	Y		Special Permit						
Gas Type	134A		Tare	1020		Test Regime	JDBA					
VIN Plate Made / Attached	Checked JS		Etched			Checked	MD					

Detailed Registration Certificate		Statement Compliance		Proof of Ownership	—
Export / Dereg Certificate	—	ADR / EEC / ECE / FMVSS / CMVSS		LHD / SIV Permit	
LVVTA Plate / RFID Tag		Structural repair Cert. / LT400		Immigrants Exemption	

Rejected Items front tyres no stds. 175/6514  
 REAR TYRES NOT MATCHING PAIR. (ONE ASSUMPTION, ONE NOT)  
 PREVIOUS REPAIRS TO RH SILL / RIF DOOR (LOWER) DOOR REFER TO REPAIR CERTIFICATE FOR ASSESSMENT.  
 POLISH, FOCUS + ALIGN HEADLIGHTS (NO CUT-OFF/PATTERNS)

NOTE -  
 Front BRACE PADS LOW (3.3mm)  
 MINOR SUBFRAME DAMAGE - F SUBFRAME  
 MINOR DENT RH A PILLAR (CANT RAIL)

WoF Authority Number	WoF Label	WoF Expiry	/	/				
Initial Inspection	19/8/24	PASS	FAIL	Recheck Inspection	/	/	PASS	FAIL
Inspector ID	4085 ISSUED	Inspector ID	4085 ISSUED	Signature				

Signature