

Customer Details **Autaworld** Order No. Site No. **6058**

**IBC**

VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS, OR ANOTHER COMPLETE INSPECTION IS TO BE CARRIED OUT



Vehicle Information

VIN	7 A T O C I 3 9 X 2 4 2 0 0 7 0 2															
Chassis	GHSFP-200702						Reference	MS6058								
Vehicle Type	07			N/U/R or SU			Border Check	21-9-24								
1st NZ Reg							Engine No	15 covered.								
Prev Country	JPN			1st Reg Date			3/12									
Basic Colour	Brown						Second Colour									
Make	Mazda						Model Atenza									
Sub Model							Indust. Model	DBA-GHSFP								
Vehcl. Year	2012		Body Type		SC		Variant 10Z									
GVM	1705		CC Rating		2488		Engine Type		01				Imported LHD		N	
Assembly Type	1						Odometer		36912.				Altern Fuel		-	
Class	MA						No. of Axles		2				ODO Unit		1C	
A/C Fitted	Y						FIS		Y				Orig. Country		JPN	
Gas Type	134A						Tare		1430				Special Permit			
Gas Type	134A						Tare		1430				Test Regime		JDBA.	
VIN Plate Made / Attached	Checked		J		4		Etched						Checked			

Detailed Registration Certificate		Statement Compliance		Proof of Ownership	
Export / Dereg Certificate	/	ADR / EEC / ECE / FMVSS / CMVSS		LHD / SIV Permit	
LVVTA Plate / RFID Tag		Structural repair Cert. / LT400		Immigrants Exemption	

Rejected Items **Speedo Plz.**  
 ① Repair front left chassis rail, Refy to Repair Centre  
 ② All Tyres cracked x4

NOTES, Front + Rear Subframe has been painted

WoF Authority Number	WoF Label	WoF Expiry	/	/				
Initial Inspection	4/12/24	PASS	FAIL	Recheck Inspection	/	/	PASS	FAIL
Inspector ID	U. Sadana	4085 ISSUED		Inspector ID	4085 ISSUED			
Signature	U. Sadana			Signature				