

Customer Details Remarkable Cars

Order No.

Site No. 6058

VEHICLES MUST BE RECHECKED WITHIN 20 WORKING DAYS, OR ANOTHER COMPLETE INSPECTION IS TO BE CARRIED OUT



Vehicle Information

VIN	7	A	T	0	D	H	1	2	X	2	5	2	0	0	3	9	3			
Chassis	HV37-200393										Reference ms6058									
Vehicle Type	07					N/U/R or S					u									
1st NZ Reg											Border Check 19/07/2025									
Prev Country	JPN					1st Reg Date 02/2014					Engine No VQ35-HM34 cored									
Basic Colour	Orange										Seats 5									
Make	Nissan										Model Skyline									
Sub Model	Hybrid					Indust. Model DAA-HV37					Variant 0002									
Vehcl. Year	2014					Body Type SL					Imported LHD NO									
GVM	2035					CC Rating 3498					Engine Type 07									
Assembly Type	01					Odometer 119489					ODO Unit km									
Class	MA					No. of Axles 2					Orig. Country JPN									
A/C Fitted	Y					FIS Y					Special Permit									
Gas Type	134a					Tare 1760					Test Regime JDAA									
VIN Plate Made / Attached	Checked LN					VJ					Etched					Checked				

Detailed Registration Certificate		Statement Compliance		Proof of Ownership
Export / Dereg Certificate	✓	ADR / EEC / ECE / FMVSS / CMVSS		LHD / SIV Permit
LVVTA Plate / RFID Tag		Structural repair Cert. / LT400		Immigrants Exemption

Rejected Items

① Left front & Both rear shocks leaking

② Rear Diff Bush Leaking.

③ Right front wheel side to side play.

WoF Authority Number WoF Label WoF Expiry / /

Initial Inspection	09/09/25	PASS	FAIL	Recheck Inspection	/	/	PASS	FAIL
Inspector ID	BSW	4085 ISSUED		Inspector ID	4085 ISSUED			
Signature				Signature				